


This document is a tool to help ensure appropriate due diligence has been taken prior to site clearance/works. Evidence is required to demonstrate all tree clearance has been suitably reviewed and can be justified.

Note: this document should be read in conjunction with the HS2 Tree Panel Terms of Reference

| | | | | |
|--|---|------------------|------------|-----------------|
| | Name | Signature | | Date |
| Application made by: | CSJV | | | 25/09/2020 |
| Location (Sector/Site Name): | Sector 1 | | | |
| LAA/LAP/Site Reference | Granby Terrace Bridge Utility Diversions | | | |
| Work Package number: | Po81 | | | |
| Date of Tree Panel: | 25/09/2020 | | | |
| Site Description: | | | | |
| Reason for clearance: | The purpose of the vegetation removal is to allow access for the excavator to carry out works associated with the Utility diversions around Granby Terrace Bridge. The tree's sit less than a metre from the edge of the utility trench, preventing the excavators from being able to work. The tree roots are at threat from extensive damage during the excavation works. | | | |
| Drawing Reference No: | N/A | | | |
| | Yes | No | N/A | Comments |
| Has the Stage 1 Survey been completed and logged on the Register | X | | | |
| | Yes | No | N/A | Comments |
| Has the Stage 2 Survey been completed with retention and protection measures logged on the Register | | X | | |
| Have all practicable means to negate need for works to tree been investigated? Please provide details | Yes, however the trees interface with the excavation associated with the Utility diversion works. | | | |
| Trees Affected and Scope of Works: <i>[Quote unique tree ID's and brief description of scope of works]</i> <u>Harrington Street</u> | | | | |

Site Sketch/ Diagram / Photos attached

The 4 trees on Harrington Street that require removal.



| Tree ID | Species |
|----------------|--------------|
| LP01138_T_F283 | Norway Maple |
| LP01138_T_F278 | Silver Birch |
| LP01138_T_F265 | Silver Birch |
| LP01138_T_F245 | Norway Maple |



Tree Panel Outcomes

| | | Proposal Endorsed/Not Endorsed: | Endorsed with conditions |
|------------|---|---------------------------------------|-----------------------------|
| Conditions | <ul style="list-style-type: none"> -Site visit with HS2, CSJV, and LBC shows that the Norway Maples cannot feasibly be retained. -CSJV to update on timing of removal to allow for a community response to the proposal. -CSJV to pursue replanting in the area if possible. | | |